Fig. 1

## HEAT & MASS TRANSFER CONFIGURATION METHOD




Fig. 2





Fig. 3










Fig. 5












Fig. 10

Fig. 11




Fig. 12





Fig. 13



6000

Fig. 14

WORK
INPUT

HEAT AND MASS
TRANSFER SYSTEM

7860

Fig. 15

2100




Fig. 16








Fig. 17





















Fig. 37



15/25





LHV CYCLE EFFICIENCY [%]







Fig. 40








Fig. 42





Fig. 43








Fig. 45




Fig. 46




Fig. 47

